PCE Americas Inc.	PCE Instruments UK Ltd.
711 Commerce Way	Units 12/13
Suite 8	Southpoint Business Park
Jupiter	Ensign way
FL-33458	Hampshire / Southampton
USA	United Kingdom, SO31 4RF
From outside US: +1	From outside UK: +44
Tel: (561) 320-9162	Tel: (0) 2380 98703 0
Fax: (561) 320-9176	Fax: (0) 2380 98703 9
info@pce-americas.com	info@pce-instruments.com

www.pce-instruments.com/english
www.pce-instruments.com

Digital Clamp PCE-CM 3-ICA

Clamp meter PCE-CM 3-ICA incl. ISO Calibration Certificate
Fork Clamp Up to 200 A AC / AC / DC Voltage Measurement / Simple Current
Measurement / LC display / Continuity test / Thermometer

The fork current clamp PCE-CM 3 is used for quick and easy AC measurements. For current measurement, the fork current clamp is placed over the current-carrying conductor. The PCE-CM 3 Fork Clamp is particularly suitable for the measurement of AC in distributions and wherever circuits must not be interrupted. The current measuring range extends from 0 ... 200 A. In addition to the current measurement, the fork current clamp can be used to measure DC and AC voltages up to 600V, resistances, capacitances and even temperatures. The measured values are displayed on the illuminated display of the fork current clamp.

The compact dimensions and the low weight distinguish this current clamp as well as the robust housing. This makes the PCE-CM 3 fork clamps the perfect companion for installers and service technicians.

- Digital Multimeters up to 200 A
- Compact dimensions
- Robust plastic housing
- Multimeter functions
- Battery operation
- Backlit LCD
- **Incl. ISO Calibration Certificate**

Specifications:

DC

Measuring range	Resolution	Accuracy
4V DC	1 mV	± (1.2% of measured value + 2 digits)
40V DC	10 mV	± (1.5% of measured value + 2 digits)
400V DC	100 mV	± (1.5% of measured value + 2 digits)
600V DC	1V	± (2% of measured value + 2 digits)

Input impedance	10 MΩ
Overvoltage protection	600V DC
	600V AC RMS

AC

Measuring range	Resolution	Accuracy
4V AC	1 mV	± (1.5% of measured value + 5 digits)
40V AC	10 mV	± (1.5% of measured value + 2 digits)
400V AC	100 mV	± (1.5% of measured value + 2 digits)
600V AC	1V	± (2% of measured value + 2 digits)

Input impedance	10 MΩ	
Overvoltage protection	600V DC	
	600V AC RMS	
Frequency range	50 ... 400 Hz	

Alternating current

Measuring range	Resolution	Accuracy
200 A AC	100-mA	± (3.0% of measured value + 5 digits)

Overload protection	200 A AC	
Frequency range	50 ... 60 Hz	

Resistance

Measuring range	Resolution	Accuracy
400 Ω	0.1 Ω	± (1% of measured value + 4 digits)
4 kΩ	1 Ω	± (1.5% of measured value + 4 digits)
40 kΩ	10 Ω	± (1.5% of measured value + 4 digits)
400 kΩ	100 Ω	± (1.5% of measured value + 4 digits)
4 MΩ	1 kΩ	± (2.5% of measured value + 4 digits)
40 MΩ	10 kΩ	± (3.5% of measured value + 4 digits)

Overvoltage protection	250V DC	
	250 AC RMS	
Connection thermocouple	Type K connection with adapter	

Capacity

Measuring range	Resolution	Accuracy
4 nF	0.1 nF	± (5% of measured value + 20 digits)
40 nF	1 nF	± (3% of measured value + 5 digits)
400 nF	10 nF	± (3% of measured value + 5 digits)
4 µF	100 nF	± (3% of measured value + 5 digits)
40 µF	1 µF	± (3% of measured value + 5 digits)
100 µF	10 µF	± (3% of measured value + 10 digits)

Overvoltage protection	250V DC	
	250 AC RMS	

Check feature	Test	Display
Diode test	Test current: 0.5-mA Reverse Voltage: 1.5V	Forward voltage of the diode
Continuity test	Open circuit Voltage 0.5V	Noise when resistance <50 Ω

Overvoltage protection	250V DC	
	250 AC RMS	

General technical specifications

Jaw Capacity	About 17 mm / .7 in
Display	4000 digit LCD with backlight
Continuity test	Noise when resistance <50 Ω
Test current	About 0.5-mA
Open circuit voltage	< 2V DC
Battery indicator	Battery icon when battery voltage low
Display overrange	OL appears in the display
Refresh rate display	3 Hz
Temperature sensor	Thermocouple type K
Input impedance	10 MΩ

Operating conditions	5 ... 40°C / 41 ... 104°F, 80% rh non-condensing
Storage conditions	-20 ... 60°C / -4 ... 140°F, 80% rh non-condensing
Operating altitude	< 2000 m / 6561 ft
Power supply	2 x 1.5V AAA battery
Automatic shutdown	30 minutes
Security conditions	IEC1010-1 (2001)
	CAT II 1000V
	CAT III 600V
Pollution degree	2

Delivery scope:

1 x Clamp meter PCE-CM 3
2 x Test leads
2 x Measuring tip
1 x Adapter thermocouple
1 x Thermocouple type K
2 x AAA batteries 1.5V
1 x User manual
1 x ISO Calibration Certificate