



DT-3385/3386

Professional Heavy Duty AC, AC/DC True RMS Autoranging Clamp Meters with Flexible Clamp

The 3385 series clamp meters offer all needed features for measurement, design for perfectly handhold and tight place testing. A large backlit display (on most models) is easy to see and a handy Display Hold keeps measurements on the display. Flexible current probe expands the measurement range to 2500ACA.



- I Double molded plastic housing
- I True RMS measurement for ACV & ACA
- I Flexible current probe expands the measurement range to 3000 ACA for all models
- I Dual type K inputs for temperature measuring support more application. (3387/3388)
- I Flexible current probe expands the measurement range to 3000 ACA

Specifications				
Function	Max. Range	Basic Accuracy	3385	3386
Voltage DC	1000V	$\pm(0.1\%+4d)$	*	*
Voltage AC	1000V	$\pm(1.0\%+3d)$	*	*
Current DC	1000A	$\pm(2.5\%+5d)$		*
Current AC	1000A	$\pm(2.5\%+5d)$	*	*
Resistance	50M Ω	$\pm(3.0\%+5d)$	*	*
Temperature	1000°C/ 1832°F	$\pm(1.0\%+2.5^\circ\text{C}/4.5^\circ\text{F})$	*	*
Capacitance	5mF	$\pm(3.5\%+10d)$	*	*
Frequency	10MHz	$\pm(0.3\%+2d)$	*	*
ACA flexible clamp	3000A	$\pm(2.8\%+8d)$	*	*
Continuity check	Buzzer sounds at 50 Ω			
Diode test	Test current 0.3mA			

Features	3385	3386
Current measurement	AC	AC/DC
LCD display counts with backlight	50000	50000
3000A ACA Flexible clamp	*	*
AC True RMS	*	*
Flashlight	*	*
Data Hold & Peak Hold	*	*
Max / Min	*	*
REL (Zero) Function	*	*
Auto Power Off	*	*
Low battery indication	*	*
1.9" (48mm) Jaw opening	*	*
NCV Detection & flashlight	*	*
Inrush Current	*	*

Size(HxWxD): 230mm x 76mm x 40mm

Weight: 315g

Accessories: Test leads, gift box with carrying case, Temperature probe and 9V battery.

