

DT-3390/3391/3391W/3392/3392W/3392BT/3395

1000A AC, AC/DC Clamp Meters

CEM

3391/3392/3395 Series Professional True RMS Clamp Meters provide accurate AC, AC/DC current and voltage readings regardless of waveforms. These meters can be used in most industrial and commercial applications where non-linear loads distort the Current or Voltage waveform.

1000A True RMS

Peak Hold Function(3392/3392W/3392BT)



EMC & LVD
EN: 61326



EN: 61010-1
EN: 61010-20-032
EN: 61010-20-033



www.tuv.com
ID 1419032229



Model 3392



Model 3391

Features

	3390	3391/3391W	3392/3392W/3392BT	3395
True RMS measurements		*	*	*
Digital display counts	4000	4000	4000	6000
Electronic overload protection	*	*	*	*
Analog Bargraph/segments			* /41	* /61
Continuity buzzer & Diode check	*	*	*	*
Data Hold function	*	*	*	*
Peak Hold function			*	Min./Max.
Inrush current measurement				
DCA Zero function			*	*
Auto Power Off	*	*	*	*
Low battery indication	*	*	*	*
AC/DC Current	AC	AC	*	*
2" (52mm) Clamp jaw opening	*	*	*	*
NCV Detection	*	*	*	*
Bluetooth data transmission			3392BT	
Wireless USB interface		3391W	3392W	

Specifications

Function	Max Range	Basic Accuracy	Max. Resolution	3390	3391 3391W	3392 3392W 3392BT	3395
AC Current	1000 A	$\pm(2.5\%+5d)$	10mA	*	*	*	*
DC Current	1000 A	$\pm(3.0\%+4d)$	10mA			*	*
AC Voltage	600V	$\pm(0.8\%+2d)$	0.1mV	*	*	*	*
DC Voltage	600V	$\pm(1.0\%+4d)$	0.1mV	*	*	*	*
Resistance	40MΩ	$\pm(1.0\%+4d)$	0.1Ω	*	*	*	*
Capacitance	40mF	$\pm(3.0\%+5d)$	0.01nF	100μF	100μF	*	4000μF
Frequency	10MHz	$\pm(1.2\%+3d)$	0.01MHz	*	*	4kHz	*
Temperature	1000°C/1832°F	$\pm(3.0\%+5d)$	1°C/F		*	*	*

Size(HxWxD): 271mm x 100mm x 47mm

Weight: 508g

Accessories: Test leads, gift box with carrying case, 9V battery and temperature probe (3391/3391W/3392/3392W/3392BT/3395/3397)