



DT-388 Flexible AC Current Clamp meter with Datalogger

AC current True RMS measurements

4000 counts display with backlight &
Analogue Bar Graph

Electronic overload protection

Data Hold & inrush function

Inrush Current

Bluetooth interface

Jaw opening 457mm (18 in) coil

3000A ACA flexible clamp

Auto Power Off

Low battery indication



Features
AC current True RMS measurements
4000 counts display with backlight & Analogue Bar Graph
Electronic overload protection
Data Hold & inrush function
Inrush Current
Bluetooth interface
Jaw opening 457mm (18 in) coil
3000A ACA fl exible clamp
Auto Power Off
Low battery indication

Size(HxWxD): 230mm x 76mm x 40mm

Weight: 315g

Specifications	
AC current range	0.5A to 3000A AC
Resolution	0.01A
Accuracy	3% ± 5 digits (50Hz to 400Hz)
Memory	Record up to 65.000 readings
Safety rating CAT IV 600V, CAT III 1000V	

Accessories:

Gift box with carrying case, 1.5V AAA x 2 batterys, APP Software.