

DIGITAL REFRACTOMETERS (GMK-701AC/702AC)

1. The names of each part



2. BEFORE MEASUREMENT

- WITH BATTERY REMOVER, TURN LEFT THE LID OF BATTERY COMPARTMENT (BACK SIDE).
- WATCHING +/- POLES CAREFULLY, PLACE BATTERY 9V 1EA IN IT.
- IF 'CAL' SIGN APPEARS ON LCD AND DISAPPEARS, THE INSTRUMENT IS READY TO MEASURE (AUTOMATIC CALIBRATION).
- WIPE 'SAMPLE WELL' WITH CLEAN WATER & TISSUE.

3. MEASUREMENT

- DRIP TWO OR THREE DROPS OF TEST SAMPLE ON THE SAMPLE WELL ENOUGH TO COVER THE PRISM OF SAMPLE WELL.(# WHEN THE PRISM IS EXPOSED TO THE AIR OR IN CASE OF NO TEST SAMPLE ON THE SAMPLE WELL, 'ERR' SIGN APPEARS ON LCD).
- PLACE 'LIGHT COVER' ON THE SAMPLE WELL AND PRESS MEASURE BUTTON.
- AFTER (- - -) SIGN FLICKERS THREE TIMES, MEASUREMENT RESULT (BRIX %) APPEARS ON LCD FOR ABOUT TWO MINUTES.
- IF THE TEST SAMPLE IS OUT OF THE MEASURING RANGE, 'ERR' SIGN APPEARS.

4. IMPORTANT

- BEFORE EVERY MEASUREMENT, CLEAN THE SAMPLE WELL WITH WATER & TISSUE.
- WHEN 'LO BAT' SIGN APPEARS, REPLACE THE BATTERY SHORTLY.
- DO NOT STORE THE INSTRUMENT AT DAMP PLACE
- IN CASE OF NO USE FOR A LONG TIME, MAKE SURE TO REMOVE THE BATTERY.
- WARRANTY PERIOD IS 12 MONTHS FROM THE DATE OF PURCHASE.
- IN CASE OF WRONG USE, ABUSE OR MISUSE, WARRANTY WILL NOT BE GRANTED.

ACCESSORIES



Battery remover



Light cover



Bottle



Carrying bag

G-WON HITECH CO., LTD.

WOOLIM E-BIZ. CENTER 310,
#170-5, GURO-DONG, GURO-GU,
SEOUL, KOREA(152-769)
Tel : 82-2-2108-1646(DIR.)
Fax : 82-2-2108-1649
E-Mail : g-won@g-won.co.kr

Other Instruments

- | | |
|------------------------|--------------------------|
| ■ Grain Moisture Meter | ■ Seed Moisture Meter |
| ■ Wood Moisture Meter | ■ Tobacco Moisture Meter |
| ■ Flour Moisture Meter | ■ Soil Moisture Meter |
| ■ Digital Salt Meter | ■ Fruit Acidity Meter |

➤ BACK

➤ PRINT

☒ CLOSE

