











8516 light meter provides accurate display light level in terms of Foot Candles FC or LUX over wide range. Just turning the Function Switch to select the "lux" scale and setting the range to desired range, then removing the light detector to light source in a horizontal position and reading the illuminance norminal from the LCD display. When the measurement is completed, replace the light detector from the light source.

Feature	es	
2.4" TFT co	olor display	
Auto Rangi	ng	
Max/Min/A	VG function	
Auto Powe	Off	
Low battery	v indication	
Selectable l	FC/Lux unit	
Capacity fo	r data logging (99 readings)	
Total accura	acy: for C.I.E standard illuminate A(2856K)	
Bluetooth i	nterface with Smart phone APP	

Specifications		
Measuring range	400,000Lux	
Accuracy	±5%±10d(<10,000Lux) ±10%±10d(>10,000Lux)	
Max Resolution	0.1Lux/0.01Fc	
Bluetooth interface	*	

Size(HxWxD): 185mm x 68mm x 45mm

Weight: 248g

Accessories :

3.7V Li-battery, USB cable, software, Carrying case

and Gift box.