

Digital Clamp Meter PCE-DC3-ICA

Digital Clamp Meter 2/80 Amp; AC/DC (of high accuracy) incl. ISO Calibration Certificate

The Digital Clamp Meter has been developed to determine indirectly, the AC/DC currents with high accuracy. A non-contact digital clamp meter and a torch to illuminate the area being measured, have been integrated into this device. The small size of this Digital Clamp Meter, makes it possible to use in small spaces with limited access. The large illuminated display of this Digital Clamp Meter guarantees clear readings in dark places such as in distribution boards. The non-contact digital multimeter will help you when exposed to potential risk and to locate with precision, break points in cables within distribution boards, etc.

- 4 digit LCD display with backlighting
- AC/DC current measurement up to 80 Amps
- Save zero function
- DCA Current tester, non-contact
- Integrated light to illuminate measured area
- Automatic range selection
- Clamp diameter: 18 mm / .7 in
- Incl. ISO Calibration Certificate

Specifications:

AC current (50 / 60 Hz)	Range / Resolution / Accuracy 2 A / 1-mA / $\pm 2.8\% + 10$ dgt 80 A / 100-mA / $\pm 3.0\% + 8$ dgt
DC current	Range / Resolution / Accuracy 2 A / 1-mA / $\pm 3.0\% + 10$ dgt 80 A / 100-mA / $\pm 3.0\% + 8$ dgt
AC overload protection (Non-contact)	100V AC up to 600V AC 50 / 60 Hz
Flashlight illumination	White LED
Conductor diameter	18 mm / 0.7 in maximum
Display	3 2/3 digit LCD display with backlighting
Power	2 - 1.5V AAA batteries
Casing	PVC
Dimensions	164 x 65 x 32 mm / 6.4 x 2.5 x 1.2 in
Weight	175 g / < 1 lb
Standards	EN61010-1; CAT II / 600V EN61010-2-032; CAT III / 300V

Delivery scope:

- 1 x Clamp Meter PCE-DC 3
- 1 x Case
- 2 x Batteries
- 1 x User's manual
- 1 x ISO Calibration Certificate