



- **ST9617 Humidity & Temperature Meter**



Product No.: ST9617

SPECIFICATIONS

Temperature range	-10~50°C(±1°C)
Humidity range	5%RH~98%RH(±3%RH)
Resolution	0.1°C/0.1%RH
Refresh Resolution	2 times/sec
°C/°F selection	√
Data hold function	√
Max/Min reading function	√
Auto/ Manual Power Off	√
Large LCD Temperature/Humidity Dual display	√
High/Low Humidity Alarm Function	√
Colour Display	√